

# GAHAGAN & BRYANT ASSOCIATES

P.O. BOX 18505 TEL. 813-879 5871

TAMPA, FLORIDA 33679

## LOG OF BORING

SUBJECT Jupiter Island  
 BORING LOCATION St. Lucie Inlet  
 X - 767,630 Y - 1,030,320  
 GROUNDWATER DEPTH \_\_\_\_\_ DATE \_\_\_\_\_  
 DRILL ROD SIZE AW CASING SIZE BW  
 BORING BEGUN \_\_\_\_\_ BORING COMPLETED \_\_\_\_\_  
 TIME AT START 0830 TIME AT FINISH 0930  
 TIDE AT START +1.4 TIDE AT FINISH +0.9  
 GEOLOGIST \_\_\_\_\_

BORING NO. 26  
 CLIENT Jupiter Island  
 DATE 7-8-76 SHEET 1 OF 2  
 DRILL RIG Bore Hog  
 DRILLER Rowland  
 LENGTH OF CASING SET 20'  
 GROUND ELEVATION \_\_\_\_\_ DATUM MLW

ELEVATION	DEPTH IN FEET	SOIL GRAPH	MATERIAL DESCRIPTION	REMARKS	SAMPLE NUMBER	BLOWS/FOOT		DEPTH IN FEET
						ON SAMPLE	ON CASING	
	1							1
	2							2
	3							3
	4							4
	5							5
	6							6
	7							7
	8							8
	9							9
	10							10
	11							11
10.6	12		Water					12
	13		Fine Gray Sand		26-1	1	7	13
	14					13	26	14
	15						20	15
	16						38	16
15.9	17		Fine Sand with Shell Fragments and Crushed Shell		26-2	15	11	17
	18					8	10	18
	19						18	19
19.0	20						38	20

BORING NO. 26

DATE 7-8-76 SHEET 2 OF 2

ELEVATION	DEPTH IN FEET	SOIL GRAPH	MATERIAL DESCRIPTION	REMARKS	SAMPLE NUMBER	ON SAMPLE	ON CASING	DEPTH IN FEET
	21				26-3	25		21
21.1	22		Fine Sand			9		22
	23							23
	24							24
	25							25
	26							26
	27							27
	28							28
	29							29
	30							30
	31							31
	32							32
	33							33
	34							34
	35							35
	36							36
	37							37
	38							38
	39							39
	40							40
	41							41
	42							42
	43							43
	44							44
	45							45
	46							46