

DRILLING LOG		DIVISION South Atlantic		INSTALLATION Jacksonville District		SHEET 1 OF 1	
1. PROJECT Ft. Pierce, FL, Shore Protection Project				10. SIZE AND TYPE OF BIT 4"vibracore			
2. LOCATION (Coordinates or Station) X=1139,207 Y=749,709				11. DATUM FOR ELEVATION SHOWN (TBM or MSL) Mean Low Water, -1.2' NGVD			
3. DRILLING AGENCY Alpine Ocean Seismic Survey, Inc.				12. MANUFACTURER'S DESIGNATION OF DRILL Vibracore			
4. HOLE NO. (As shown on drawing title and file number) CB-STL-B2				13. TOTAL NO. OF OVERBURDEN SAMPLES TAKEN disturbed: 0 undisturbed: 0			
5. NAME OF DRILLER L. Oblinger				14. TOTAL NUMBER OF CORE BOXES			
6. DIRECTION OF HOLE <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED				15. ELEVATION GROUND WATER			
7. THICKNESS OF BURDEN 0 Ft.				16. DATE HOLE STARTED COMPLETED 12/11/94 12/11/94			
8. DEPTH DRILLED INTO ROCK 0 Ft.				17. ELEVATION TOP OF HOLE -32 Ft.			
9. TOTAL DEPTH OF HOLE 10.0 Ft.				18. TOTAL CORE RECOVERY FOR BORING 100 %			
				19. SIGNATURE OF Geologist J. Vann, G. Zarillo			
ELEV.	DEPTH	LEGEND	CLASSIFICATION OF MATERIALS (Description)	CORE REC %	SAMPLE NUMBER	REMARKS	
-32.0	.0					-32.0	0
			SAND, poorly graded, fine to medium grained quartz, brown, (SP)		B2-1.3		2.5
			Lens of Shell hash at -35.7'				
-36.5	4.5			100			5
			SAND, poorly graded, fine grained quartz, (SP)		B2-5.6		
-37.7	5.7						
			Limestone pebbles at -37.0'		B2-7.2		7.5
			SAND, poorly graded, trace gravel, whole shells, trace limestone pebbles, trace silt, brown-gray, (SP)				
-41.4	9.4						
-42.0	10.0				B2-9.6	-42.0	10
			Silty SAND, poorly graded, medium to coarse grained quartz and shell, little calcareous clay and silt, gray, (SP-SM)				12.5
			NOTE: 1. Soils are field visually classified in accordance with the Unified Soils Classification System.				15
							17.5
							20
							22.5