

<b>DRILLING LOG</b>		<b>DIVISION</b>		<b>INSTALLATION</b>		<b>SHEET 1 OF 1 SHEETS</b>	
<b>1. PROJECT</b> Walton County Borrow Area A Walton County, Florida				<b>9. SIZE AND TYPE OF BIT</b>			
<b>2. BORING DESIGNATION</b> WA-26				<b>LOCATION COORDINATES</b> X = 1,385,992 Y = 479,418		<b>10. COORDINATE SYSTEM/DATUM</b> Florida State Plane North	
<b>3. DRILLING AGENCY</b>				<b>CONTRACTOR FILE NO.</b>		<b>11. MANUFACTURER'S DESIGNATION OF DRILL</b> Vibracore	
<b>4. NAME OF DRILLER</b> Alpine				<b>12. TOTAL SAMPLES</b>		<b>13. TOTAL NUMBER CORE BOXES</b>	
<b>5. DIRECTION OF BORING</b> <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED				<b>DEG. FROM VERTICAL</b>		<b>BEARING</b>	
<b>6. THICKNESS OF OVERBURDEN</b> 0.0 Ft.				<b>14. ELEVATION GROUND WATER</b>		<b>15. DATE BORING</b> 08-28-06 16:04	
<b>7. DEPTH DRILLED INTO ROCK</b> 0.0 Ft.				<b>16. ELEVATION TOP OF BORING</b> -72.1 Ft.		<b>17. TOTAL RECOVERY FOR BORING</b> 15.9 Ft.	
<b>8. TOTAL DEPTH OF BORING</b> 18.7 Ft.				<b>18. SIGNATURE AND TITLE OF INSPECTOR</b>			

ELEV. (ft)	DEPTH (ft)	LEGEND	CLASSIFICATION OF MATERIALS Depths and elevations based on measured values	% REC.	BOX OR SAMPLE	REMARKS
-72.1	0.0					
					WA-26 0'	Sample #WA-26 0', Depth = 0.0'
					WA-26 1.5'	Sample #WA-26 1.5', Depth = 1.5'
					WA-26 3.0'	Sample #WA-26 3.0', Depth = 3.0'
			Medium sand. Burrows at depth of 2.3' to 2.5'. Shells at depth of 1.2' to 1.9', 3.5' to 3.7', 4.6' to 4.7', (SP).			
-78.9	6.8					
			Carbonate-cemented sediment. Shells at 8' to 8.2'..			
-87.1	15.0					
			Medium sand, with shells at the top and organics in the lower section., (SP).			
-88.4	16.3					
			End of Boring			

FLORIDA DEP ROSS WALTON COUNTY DETAIL PHASE II.GPJ FL DEP ROSS.GDT 09/12/07