

DRILLING LOG		DIVISION <b>SOUTH ATLANTIC</b>		INSTALLATION <b>MOBILE DISTRICT</b>		Hole No. <b>V-31-94</b> SHEET <b>1</b> OF <b>1</b> SHEETS	
1. PROJECT <b>BAY CO FL OFFSHORE PANAMA CITY BEACHES NOURISHMENT</b>				10. SIZE AND TYPE OF BIT <b>3.5" x 25' VIBRACORE</b>			
2. LOCATION (Coordinates or Station) <b>ZONE FLN: N 451178 E 1550514</b>				11. ELEVATION DATUM <b>NGVD, FOOT U.S.</b> COORDINATE DATUM <b>STATE PLANE, NAD27, FOOT U.S.</b>			
3. DRILLING AGENCY <b>TET, INC.</b>				12. MANUFACTURER'S DESIGNATION OF DRILL <b>VIBRACORE</b>			
4. HOLE NO. (As shown on drawing title and file number) <b>V-31-94</b>				13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN		DISTURBED <b>3</b> UNDISTURBED <b>0</b>	
5. NAME OF DRILLER <b>CHARLIE WESTON</b>				14. TOTAL NUMBER CORE BOXES <b>0</b>			
6. DIRECTION OF HOLE <input checked="" type="checkbox"/> VERTICAL <input type="checkbox"/> INCLINED      DEG. FROM VERTICAL				15. ELEVATION GROUNDWATER			
7. THICKNESS OF OVERBURDEN <b>-</b>				16. DATE HOLE STARTED <b>28 NOV 94</b> COMPLETED <b>28 NOV 94</b>			
8. DEPTH DRILLED INTO ROCK <b>-</b>				17. ELEVATION TOP OF HOLE <b>EL. -32.1</b>			
9. TOTAL DEPTH OF HOLE <b>15.0 (EL. -47.1)</b>				18. TOTAL CORE RECOVERY FOR BORING <b>0</b>			
				19. SIGNATURE OF INSPECTOR <b>BRAD RALPH</b> DRAFTED <input type="checkbox"/> CHECKED <input type="checkbox"/> BCR      BCR			
ELEVATION <sub>a</sub>	DEPTH <sub>b</sub>	LEGEND <sub>c</sub>	CLASSIFICATION OF MATERIALS (Description) <sub>d</sub>	% CORE RECOVERY OR W.C. <sub>e</sub>	BOX OR SAMPLE NO. <sub>f</sub>	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) <sub>g</sub>	
-32.1	0.0	• • • • •	(SP) Gray to white medium to fine SAND, trace shell	87% RECOV	S-1	LAB: (SP), 4% FINES (FINER THAN #200 SIEVE)	
	3.0	• • • • •					
	6.0	• • • • •					
	9.0	• • • • •	(SP) Light brown medium to fine SAND		S-2	LAB: (SP), 2% FINES	
	12.0	• • • • •			S-3	LAB: (SP), 4% FINES	
	13.0	• • • • •					
-45.1	13.0	X	SAMPLE NOT RECOVERED		X		
-47.1	15.0	X			X		
						B.O.H.	