Hole No. S1T5

DRILLING LOG	DIVISION SOUTH ATLANTIC	INSTALLATION MOBILE DISTRICT	SHEET 1 OF 1 SHEETS

1. PROJECT: SANTA ROSA COUNTY
2. LOCATION (Coordinates or Station): E: 1210427.05 N: 501138.52
3. DRILLING AGENCY: ALPINE OCEAN SEISMIC SURVEY, INC.
4. HOLE NO. (As shown on drawing title and file number): S1T5
5. NAME OF DRILLER: FRANCESCO GERVASI
6. DIRECTION OF HOLE: [X] VERTICAL [ ] INCLINED DEG. FROM VERTICAL
7. THICKNESS OF OVERBURDEN: N/A
8. DEPTH DRILLED INTO ROCK: N/A
9. TOTAL DEPTH OF HOLE: 18.62'
10. SIZE AND TYPE OF BIT: 4" x 20' VIBRACORE
11. ELEVATION DATUM: MLLW
COORDINATE DATUM: NAD-83
12. MANUFACTORER'S DESIGNATION OF DRILL: R/V ATLANTIC TWIN
13. TOTAL NO. OF OVER-BURDEN SAMPLES TAKEN: DISTURBED N/A; UNDISTURBED N/A
14. TOTAL NUMBER CORE BOXES:
15. ELEVATION GROUNDWATER: 62.3' UNDERWATER
16. DATE HOLE: STARTED 10-2-00; COMPLETED 10-2-00
17. ELEVATION TOP OF HOLE: 62.3' UNDERWATER
18. TOTAL CORE RECOVERY FOR BORING: 18.00'
19. SIGNATURE OF INSPECTOR: DRAFTED TAM; CHECKED

ELEVATION a	DEPTH b	LEGEND c	CLASSIFICATION OF MATERIALS (Description) d	% CORE RECOVERY OR W.C. e	BOX OR SAMPLE NO. f	REMARKS (Drilling time, water loss, depth of weathering, etc., if significant) g SPT BLOWS/FT
			(SP) MED-FINE QTZ SAND, TRACE SHELL		0.0-0.3	MUNSELL 10YR 8/1 (WHITE)
					2.5-2.8	
-65.6	3.3		(CL) CLAY LAYER			MUNSELL 10YR 4/1 (DK. GRAY)
-66.3	4.0		(SP) FINE QTZ SAND			MUNSELL 10YR 8/1 (WHITE)
	5.0		(SM) MOTTLED AND BURROWED SILTY ORGANIC RICH QTZ SAND		4.7-5.0	MUNSELL 10YR 4/1 (DK. GRAY)
					6.5-6.8	
					8.5-8.8	
	10.0					
-73.5	11.2				10.5-10.8	
-74.8	12.5		(SP) MED-CSE QTZ SAND			MUNSELL 10YR 5/4 (YELLOWISH BROWN
			(SP) SILTY, FINE QTZ SAND			MUNSELL 10YR 7/2 (LT. GRAY)
					13.5-13.8	
	15.0				14.7-15.0	
					16.5-16.8	
-79.8	17.5					